


CORNER RECORD

Agency Index BK. 21 Pg 18

Document Number 20180085

City of _____ County of Placer, California

Brief Legal Description CENTERLINE MONUMENT AS SHOWN ON I-MAPS-61, O.R.P.C.



CORNER TYPE

SEC 15 Government Cor. ☐ Control ☐
T15N Meander ☐ Property ☐
R16E Rancho ☐ other ☒

Date of Survey JULY 30, 2018

COORDINATES (OPTIONAL)

N. _____ E. _____
Elevation _____
Units ☐ Metric ☒ U.S. Survey Foot
Horizontal Datum _____
Zone _____ Epoch Date _____
Vertical Datum _____

☐ Complies with Public Resources code § 8801-8819
☐ Complies with Public Resources code § 8890-8902

PLS Act Ref:

☐ 8765(d)

☒ 8771

☐ 8773

☐ Other

Corner/ Monument:

☒ Left as Found

☐ Established

☒ Rebuilt

☐ Pre-Construction

☐ Found and Tagged

☐ Reestablished

☐ Referenced

☐ Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☒ See sheet # 2 for description(s):

FOUND MONUMENT, PER "PLAT OF ALPINE PEAKS UNIT NO. 1", RECORDED IN BOOK I OF MAPS, PAGE 61, P.C.R., FROM FOUND MONUMENT ESTABLISHED REFERENCE POINTS PRIOR TO NEW PAVEMENT OVERLAY, FROM REFERENCE POINTS SET MAG NAIL W/ 1-1/4" BRASS TAG STAMPED "PLACER CO. SURVEYOR" CENTERED OVER THE FOUND MONUMENT AFTER PAVEMENT OVERLAY.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Professional Land Surveyors' Act on OCTOBER 4, 2018.

Signed [Signature]

P.L.S. or R.C.E. No. 7941



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed OCTOBER 9, 2018.

Signed [Signature]

P.L.S. or R.C.E. No. 6584

County Surveyor

County Surveyor's Comment:



